



TECHNICAL BULLETIN

To: HGNSS Customers
From: Hemisphere GNSS
Date: February 24th, 2022
Reference #: TB1302022-02-24

PRODUCTS AFFECTED:

- Hemisphere GNSS VS1000 (940-3120-10; 752-0029-10)

SCOPE:

HGNSS has released new menu firmware (1.00.12) for the positioning products listed above. This new firmware release represents Hemisphere GNSS ongoing commitment to ensure HGNSS customers experience the best possible performance from their products.

The enhancements and improvements available with this new firmware are outlined below:

Firmware Release Notes
<p>Version: 1.00.12</p> <ul style="list-style-type: none">• Improved display management when WiFi is disabled.



Product specific release notes and binary files can be downloaded on our website at WWW.HGNSS.com/Resources-Support/Software

FURTHER INFORMATION:

If you have any further questions, please contact Hemisphere GNSS technical service department at +1 (480) 348-6380. For support via email, please contact TechSupport@HGNSS.com or consult WWW.HGNSS.COM for the latest HGNSS product and software information.

This document is provided for technical support purposes only.
Please refer to the product documentation for warranty, license and
safety information associated with the product.